Work	Ord	er ID	719	961
	$\mathbf{v}_{\mathbf{i}}$	\sim \sim	/ 1/	<i>,</i> \mathbf{v}

Thursday, July 14, 2011 10:39:15 AM



Page 1

Item ID:

D3272-1

Accept

Setup Start

Stop



Revision ID:

Start Date:

Item Name:

Required Date: 7/29/2011

Step

QC:

7/14/2011

Start Qty: 10.00

Req'd Qty: 10.00

Date:

Cust Item ID: Customer:

Reference:

. Approvals:

Process Plan:

Date: _//_07_

Date:

Start



Run

Sequence ID/ Work Center ID

Operation

Description

Set Up/ **Run Hours** Tool ID

Plan

Code

Accept

Stop

Insp.

Draw Nbr

Revision Nbr

D3272 Rev B

100

Large Fab Large Fab

Large Fab

Memo

SQUARE ONE END BEFORE CUTTING OTHER END

1-Cut D2622-120 extrusion to 116.25" long as per Dwg D3272 using cutting table setup DT 8185-2A

2-Drill extrusion as per Dwg D3272 using Jig DT8680 for rivets.

3-Deburr

110

QC6- Inspect dimensions to drawing

0.00

Memo

0.00

(p(11.08.12 10 \$

Quality Control

Tooling:

0.00

0.00

SPC (Y/N):

Date:

Tool# 4

Qty

Reject **Qty**

Reject Number

Stamp

Dail Ac	ospace	s Llu								
W/O:			W	ORK ORDER CHAN	GES				-	
DATE	STEP	PR	OCEDURE CHA	NGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR:	Yes N	o DQ	\ :	Date:	
	R	esolution:	Dispositio	n:	QA: N	C Clos	sed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORM	IANCE (I	VCR)				
		Description of NC		Corrective Action Se	ction B		Verific	otion	Ammanal	Ammanal
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	S	ign & Date	Secti		Approval Chief Eng	Approval QC Inspector
					<u>.</u>					
		,			·					
										

Work Order ID 71961

Thursday, July 14, 2011 10:39:15 AM



Page 2

Item ID:

D3272-1

Accept



Setup Start

Stop



Revision ID:

Start Date:

Item Name:

Step

7/14/2011

Start Qty: 10.00

Req'd Qty: 10.00



Cust Item ID:

Customer:

Reference:

Approvals:

Required Date: 7/29/2011

Process Plan:

QC: _

Date:_____

Date: SPC (Y/N):

Tooling:

Set Up/

Run Hours

Date:

Date:

Run

Start



Stop

Sequence ID/ **Work Center ID**

120

Packaging

130

Operation Description

Identify as per dwg & Stock Location:

0.00

ś

0.00

Tool ID

Tool # Plan Code

A11.08.12 10 \$

Accept Qty

Reject Qty

Reject Insp. Number Stamp

Packaging

0.00

Quality Control

Memo

QC21- Final Inspection - Work Order Release

Memo

0.00

	. Johnso min							
W/O:			WORK ORDER	CHANGES				
DATE	STEP	PR	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
		,						
Part No	:	PAR #:	Fault Category:	NCR: Y	es No DC	A:	Date: _	
	Resolution:		Disposition:	QA: N/C	Closed:	· · ·	Date: _	
NCR:			WORK ORDER NON-CON	IFORMANCE (N	CR)		,	
	T .		Corrective Action	n Section B	T		Τ	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B		Verification	Annroyal	Annroyal	
DATE	STEP	Section A Initial Action Descri		Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector	
								,	
						Í			
								a ***	

Picklist Print

Thursday, July 14, 2011 10:39:25 AM

D3272-1

Work Order ID: 71961

Parent Item:

Parent Item Name: Step



Start Date: 7/14/2011

Start Qty: 10.00

Required Date: 7/29/2011

Page 1

Required Qty: 10.00

Comments:

IPP Rev:A

New Issue 07-06-09 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2622-120C		Manufactured	No	-	,	100	Each	121.7000	1	10	7 1 4	1	

Step Extrusion

Location	Loc Qty	Loc Code
HALL	112	
64409	6	
<u>68293</u> ·	106	
WA	9.7	
46910 °	2	
66970	7.7	

11.08.00.

Dail Ac	- ospace								
W/O:			WO	RK ORDER CHANG	ES				,
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					,				
					į				
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DC	QA:	_ Date: _	
	R	esolution:	Disposition	l:	_ QA: N/C (Closed:		Date: _	<u>-</u>
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NC	R)			
DATE	OTED	Description of NC		Corrective Action Section		Verif	ication	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Sec	tion C	Chief Eng	QC Inspector
1		j .	; l		ı	ı		1	1



DESIG	P	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CANAL	
CHEC	SED _	APPROVED	DRAWING NO.	REV. B
(E	1. #	D3272	SHEET 1 OF 3
DATE			TITLE	SCALE
07.0	5.18		STEP ASSEMBLY, HI LONG	NTS
Α		04.03.01	NEW ISSUE	
В		07.05.18	D3272-1 WAS D2622-120	

OT OG OF

QTY -041	QTY -042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	Х	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
` [
16	16	MS20600AD4W4	RIVET,

B

GENERAL NOTES:

- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1
 POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3
 BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.


SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE

WORK ORDER NO._________

pl11-07-14

Copyright © 2004 by DART AEROSPACE LTD


Duit Ac	ospace	LIU								
W/O:			W	ORK ORDER CHANGI	ES					
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										:
Part No	:	PAR #:	Fault Cate	egory:	NCR: Ye	es N	o DQ	A:	Date: _	
	R	esolution:	Disposition	on:	QA: N/C	Clos	sed:		Date: _	
NCR:		•	WORK ORE	ER NON-CONFORMA	NCE (N	CR)				
DATE	CTED	Description of NC		Corrective Action Section			Verific	cation	Approval	Approvai
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		n & ate	Secti		Chief Eng	QC Inspector
,										



Duit Ac	ospace i	Ltu							
W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Categ	ory:	NCR: Yes	No DQA:		Date: _	
	Res	solution:	Disposition	:	_ QA: N/C Cld	sed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR)			
DATE	OTED	Description of NC		Corrective Action Section		Verifica	tion	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
ĺ									
	1		1		1			1	



DESIGN	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CAN	
CHECKED	APPROVED	DRAWING NO. D3272	REV. B SHEET 3 OF 3
DATE		TITLE	SCALE
07.05.18		STEP ASSEMBLY, HI LONG	1:20



Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Dart Ae	rospace	Ltd									ali a g alt	
W/O:			,	V	ORK ORDER CHAN	IGES						
DATE	STEP	PROCEDURE CHANGE					Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		• • • • • • • • • • • • • • • • • • •										
Part No:		PAR #: Fault Category:				NCR: Yes No DQA: Date:						
	Re	esolution:	lution: Disposition:					QA: N/C Closed: Date:				
NCR:			WC	ORK OR	DER NON-CONFORI	MANCE	(NCR)				
DATE	STEP	Description of NC Section A	1	Initial Chief Eng	Corrective Action S Action Descriptio Chief Eng		Sign &		cation ion C	Approval Chief Eng	Approval QC Inspector	
i de la companya de l				•								
, i												